

Replacement UV lamps for GCC printers

Our experience with GCC replacement UV curing lamps is limited. Most likely this is due to the limited popularity of these printers. We are especially proud of our design which is far superior to the Far Eastern source OEM lamp.

Our lamps cure at the same rate but cost less than the OEM product. More importantly, since we manufacture the lamp ourselves, you will have your lamp far sooner than waiting from Taiwan.

GCC StellarJET printers use two (2) lamps, one on each side of the carriage. To reduce gloss banding and maintain equal UV dosage when printing bi-directionally, it is recommended that both UV lamps be replaced at the same time.

We have produced UV curing lamps for the following GCC printers

StellarJET 183 UV	StellarJET 183UVK	StellarJET K72
Stellar JET 183	Stellar JET 183 UVK	GCC StellarJET

All above printers use the same lamp: AA034

