

Replacement UV lamps for HP, Colorspan and MacDermid printers

In 2007, HP (Hewlett Packard) acquired the MacDermid Colorspan line of wide-format digital inkjet printers. The machines live on using replacement UV curing lamps from TCS Technologies. We manufacture UV lamps for all Colorspan printers including the snap-in CH231A and 109052 bulb.



We manufacture UV curing lamps for the following Colorspan printers:

72UVR	98UVR	5460
72UVX	98UVX	5465
DM98UVR	5440	9840UV
9840UV	5445	

Replacement UV inkjet lamps for Colorspan printers include:

Subzero 055A	CH234A	109052
Subzero 085	0901495	
CH231A	80044042	



MacDermid -- ColorSpan style lamps require one pay close attention to the condition of the lamp holder (lamp socket). It is imperative the lamp holder (located in UV lamp housing) be kept clean. Both time and heat cause the spring contact in the lamp holder to relax causing poor electrical contact. Inspect and replace lamp sockets at the first sign of wear. A little preventative maintenance goes a long way keeping your printer operating at peak performance. Always be sure the lamp is seated correctly in the lamp holder. It is extremely easy to think UV lamp is correctly inserted when it is not.