




## UV Curing Lamps For Hanovia

<b>Do not scale</b>		<b>431 metal</b>						
<b>UV lamp type 431 suffix style</b>								
		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2" style="text-align: center;"><b>TCS Technologies</b> 430 Sandshore Road Unit 1 Hackettstown, NJ 07840</td> </tr> <tr> <td colspan="2" style="text-align: center;"><b>UV lamp 431 metal style</b></td> </tr> <tr> <td style="width: 50%; text-align: center;"><b>7/15/2002</b></td> <td style="width: 50%; text-align: center;"><b>431 metal</b></td> </tr> </table>	<b>TCS Technologies</b> 430 Sandshore Road Unit 1 Hackettstown, NJ 07840		<b>UV lamp 431 metal style</b>		<b>7/15/2002</b>	<b>431 metal</b>
<b>TCS Technologies</b> 430 Sandshore Road Unit 1 Hackettstown, NJ 07840								
<b>UV lamp 431 metal style</b>								
<b>7/15/2002</b>	<b>431 metal</b>							


If you are looking for USA-manufactured replacement UV lamps for Hanovia equipment look no further. Hanovia UV lamps are utilized in a wide variety of industries. They come in various sizes and spectral fills. Hanovia makes excellent UV systems. Our lamps offer direct interchange with Hanovia product without sacrificing performance.

Since 1979, we have manufactured quality UV curing lamps right here in the USA. No order is too small and we ship worldwide. Our lamps are reliable and backed by 32-years of lamp-making excellence.

<b>6806A431</b>	<b>6812A431</b>	<b>6825A431</b>	<b>6838A441</b>	<b>4848AP31</b>
<b>6806A434</b>	<b>6812A432</b>	<b>6825A441</b>	<b>6838A442</b>	<b>4848AP41</b>
<b>6806A443</b>	<b>6812A441</b>	<b>6825A442</b>	<b>6838A443</b>	<b>4848AP42</b>

6806A446	6812A443	6825A443	6838A444	6850A431
6807A431	6812A445	6825A444	6838AP41	6850A441
6807A443	6812A446	6825A446	6840A431	6850A442
6807A444	6812A445	6825A444	6838AP41	6850A441
6807A491	6812A448	6825A532	6840A442	6850A461
6807A532	6812A449	6828A431	6840A443	6855A431
6808A431	6812A461	6828A433	6840A446	6855A444
6808A441	6813A441	6828A443	6842A431	6855A471
6808A442	6815A431	6828A444	6842A432	6859AP41
6808A445	6815A442	6830A431	6842A441	6860A431
6808AA42	6815A445	6830A441	6842A442	6860A433
6808AA43	6818A431	6830A442	6842A444	6860A442
6808AF441	6818A432	6830A444	6842AP41	6860A541
6809AA42	6818A433	6830A446	6842B441	6860A542
6809AA43	6818A441	6830A541	6842H431	6860H641
6810A431	6818A442	6832A431	6844A431	6863A491

6815A443	6818A451	6824A441	6828A441	6828A442
6810A432	6818A443	6832A432	4848A431	6865A431
6810A441	6818A444	6832A441	4848A441	6865A441
6810A443	6818A446	6832A444	4848A442	6865A442
6810A446	6820A431	6832B441	4848A443	6865A444
6810A447	6820A441	6836A442	4848A444	6865A445
6810A448	6821A431	6838A431	4848A445	6866AP41
6810A441	6824A431	6838A433	4848A544	6879A441
6838A445	6848A431	6848A444	6860A444	



Keep in mind, just because a lamp is from a second source does not mean inferior quality. TCS Technologies actually manufactures the lamps we sell. We are not a reseller of Chinese lamps. Our lamp quality is equal to or greater than the OEM. You receive the same quality, USA-manufactured product at a fraction of the cost.

<b>6504A431</b>	<b>6520A431</b>	<b>6532A442</b>	<b>6550A442</b>	<b>6825AP41</b>
<b>6504A435</b>	<b>6522A431</b>	<b>6538A431</b>	<b>6552A431</b>	<b>6528A433</b>
<b>6504A441</b>	<b>6524A431</b>	<b>6538A432</b>	<b>6552A442</b>	<b>6528AP44</b>
<b>6505A441</b>	<b>6524AP31</b>	<b>6538AP42</b>	<b>6552A442</b>	
<b>6504A445</b>	<b>6524A442</b>	<b>6538A444</b>	<b>6555A431</b>	
<b>6506A431</b>	<b>6524C431</b>	<b>6538B431</b>	<b>6560A431</b>	
<b>6506A432</b>	<b>6525A431</b>	<b>6538B442</b>	<b>6560A442</b>	
<b>6506A441</b>	<b>6525A441</b>	<b>6538C431</b>	<b>6560A444</b>	
<b>6506C431</b>	<b>6525A442</b>	<b>6540A431</b>	<b>6560AP41</b>	
<b>6506F431</b>	<b>6525A444</b>	<b>6540A441</b>	<b>6565A431</b>	
<b>6506I431</b>	<b>6525A451</b>	<b>6540A442</b>	<b>6565A441</b>	
<b>6508A431</b>	<b>6525A532</b>	<b>6549A443</b>	<b>6565A442</b>	
<b>6508A441</b>	<b>6525AP42</b>	<b>5440A444</b>	<b>6577A431</b>	
<b>6510A431</b>	<b>6525C431</b>	<b>6540A445</b>	<b>6577A432</b>	

<b>6510A432</b>	<b>6525I431</b>	<b>6542A431</b>	<b>6577AP42</b>	
<b>6510A441</b>	<b>6525I444</b>	<b>6542A442</b>	<b>6606A433</b>	
<b>6512A431</b>	<b>6528A441</b>	<b>6542B442</b>	<b>6606A447</b>	
<b>6512A441</b>	<b>6530A431</b>	<b>6548A431</b>	<b>6610A441</b>	
<b>6512A451</b>	<b>6530A442</b>	<b>6548A441</b>	<b>6618A442</b>	
<b>6515A431</b>	<b>6530A461</b>	<b>6548A444</b>	<b>6644A441</b>	
<b>6512C431</b>	<b>6530A443</b>	<b>6548A442</b>	<b>6648A441</b>	
<b>6510I431</b>	<b>6528A431</b>	<b>6542B431</b>	<b>6760A431</b>	
<b>6516A431</b>	<b>6532A431</b>	<b>6548AP31</b>		
<b>6518A431</b>	<b>6532A432</b>	<b>6548AP41</b>		
<b>6518C431</b>	<b>6532A441</b>	<b>6550A431</b>		

